

Glazing Issues

Tremco recommends that each glazing restoration should begin with thorough analysis, conducted by a properly equipped, licensed professional. This should include complete deglazing of the assembly to determine the best method of restoration. The glazing system should be considered integrated within the overall building envelope. The effects of restoration are relative to useful life of other aging components such as IG units and anchoring components.



- Gaskets pulling out from the corner may be a result of wrong size gasket for the opening, more movement occurring than anticipated, and/or more relaxation in the extruded rubber than anticipated.
- Tremco can provide replacement gaskets in lineal or fabricated frame formats. Go to [Investigation and Support](#) section for more details



- Gasket cracking maybe caused by one or combination of the following; ozone attack, excessive cleaning detergents removing the rubber's protective ingredients, excessive stretching and/or thin cross-section of material causing the material to prematurely heat age and crack.
- Tremco can provide replacement gaskets in lineal or fabricated frame formats. Go to [Investigation and Support](#) section for more details.



- Perimeter sealant bead is tearing as a result of differential movement between the window frame and structure.
- [Tremco Design Engineering Group](#) can assist with design of the appropriate solution and provide options where available.

For more information on Tremco's Glazing and Facade Restoration Solutions, please visit our website at www.tremcosealants.com or contact your local Tremco Sales Representative.



- Butyl tape failure as a result of excessive thermal movement of window frame allowing tape to roll out of position.
- [Tremco Design Engineering Group](#) can assist with design of the appropriate solution and provide options where available.

For more information on Tremco's Glazing and Facade Restoration Solutions, please visit our website at www.tremcosealants.com or contact your local Tremco Sales Representative.