


DYMONIC 100 AT  
FASTENER PENETRATION

EXOAIR 120

DYMONIC 100

$\frac{1}{16}$ " -  $\frac{1}{2}$ "



NOTE: FOR GAPS BETWEEN  $\frac{1}{8}$ " -  $\frac{1}{2}$ " PREFILL GAP WITH  
DYMONIC 100 PRIOR TO TREATING BOARD JOINT

*The architecture, engineering, and design of the project using the Tremco products are the responsibility of the project's design professional. All products and systems must comply with local building codes and standards. This detail is for general information and guidance only and Tremco specifically disclaims any liability for the use of this detail. The project design professional determines, in its sole discretion, whether this detail or a functionally equivalent detail is best suited for the project. This detail is subject to change without notice. Contact Tremco to ensure you have the most recent version.*

### ExoAir 120



Tremco Technical Support: 866-209-2404

Detail: Impermeable Fluid - Board Joint and Fastener Treatment

Drawn by: HDE

Checked by: CB

Scale: NTS

Date: 3/30/2022

File Name:

AVB-SI-F-BJ-01



Construction Products Group

[tremcocpg.com](http://tremcocpg.com)