

Detail: Paraseal LG at Transition over Gaps in Lagging

File Name:

Tremco Technical Support: 866-209-2404

Checked by: SP/WH

Scale: NTS

www.tremcocpg.com

Date: 3/4/2022

BSW-LG-LW-04 |▼1

